

**Problem:** Changing the spark plugs on the late model Ford F- 150 is very difficult due to the depth the spark plug is recessed in the cylinder head and lack of space working area. Conventional tools don't do the job.

**Solution:**

Spark Plug Socket (OTC #) No. 6900

- Works on 2004–newer F-150 pickups with the 5.4L 3-valve Triton V-8 engine.
- Socket extension easily fits into the spark plug tube in the cylinder head.
- 9/16 " socket end with a soft rubber insert holds and protects the plug during removal or installation.
- Drive end is 3/8" for heavy-duty use with ratchet or breaker bar.

